



H U N T E R[®]
MARINE CORPORATION
AN EMPLOYEE OWNERSHIP COMPANY

April 21, 2003

ATTENTION - 240, 260 & 270 OWNERS / DEALERS

240's - HUN24443K102 - HUN24489L203
260's - HUNFOO17J102 - HUNFOO85B303
270's - HUNK0168E202 - HUNK0172G203

Recently it was brought to our attention that a small portion of the above listed models may not have proper fuse protection for the CO alarm. This protection can be added by following the attached installation procedure.

By using this instruction sheet to install the supplied parts, it will prevent any unnecessary damage to your boat in the event of a 12-volt electrical short or a power surge.

Our belief is that most owners, with the proper tools, will be able to accomplish this up-grade in less than one hour. However, if you do not have the means or ability to do so, Hunter Marine will pay up to one hour of labor at \$50.00 per hour to have the repair made for you as a demonstrate of our appreciation for our boat owners.

Please complete the attached form and return it to Hunter Marine upon completion of this upgrade.

If you are not able to make this modification and have no knowledge of a repair facility with the ability to do so, please contact us so we may assist you in locating a repair facility.

Thank you,
Customer Service Department
Toll Free: 1-800-771-5556
Fax: 386-462-4077
customerservice@Huntermarine.com